



Integrated Device Technology, Inc.
 2975 Stender Way, Santa Clara, CA - 95054
 Phone #: (408) 727-6116 Fax #: (408) 727-2328

Errata Notification

EN #: LEN-02-01 Errata Revision #: 0
 Issue Date: May 3, 2002 Effective Date: May 3, 2002
 Product Affected: IDTQS32X384, IDTQS32XL384, IDTQS32X2384, IDTQS32XVH384

ERRATA DETAILS: ATTACHMENT Yes No

Data Sheet Errata
 Device Errata
 Device Manual Errata
 Application Notes Errata
 Other (Please Specify)

Pin names on the datasheets were swapped as follows:

<u>Pin #</u>	<u>Was (In-correct)</u>	<u>Is (Correct)</u>
34	B14	A14
35	A14	B14

IDT Web Site Location:
http://www.idt.com/products/pages/Bus_Switches.html

CUSTOMER NOTIFICATION:
 As a result of Errata listed above, IDT has decided to notify you through this Errata Notification.
 We recommend you to review this notification in details prior to the use of affected product in your application.
 Please use acknowledgement below or E-Mail to request additional information.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____ E-Mail Address: _____
 Name/Date: _____ Phone #: _____
 Title: _____ Fax #: _____

CUSTOMER COMMENTS: _____